

Table 2. Operational Issues (Continued)

Issue	Correction or Fix
<p>Security Definition update causes expensive reevaluation of all active OPC subscriptions.</p> <p>For the Feature Pack function, Point of Control, this may cause performance issues in the system when using operations such as request, accept, transfer responsibility. This happens when there are large number of active subscriptions on OPC items from Process Graphic displays.</p> <p>800xASYS-OL-5110-071</p>	<p>This problem has been corrected.</p>
<p>When the Graphic Display in the base pane of the Tabbed Workplace is pinned then opening a Graphic Display by clicking on Level 1 button may not work and the overlap is shown as blank.</p> <p>800xASYS-OL-5141-037</p>	<p>This problem has been corrected.</p> <p>Note: This problem has been corrected in 800xA Base 5.1 FP4 RevD RU1.</p>
<p>Long object names are not fully visible in the breadcrumb list (drop downs) below the tabs in the Tabbed Workplace.</p> <p>800xASYS-OL-5130-026</p>	<p>This problem has been corrected.</p> <p>The breadcrumbs (drop downs) will auto adjust to show the complete name as tabs do with respect to the MinWidth and MaxWidth configuration specified in the Tab Appearance. The same MinWidth and MaxWidth configuration specified in the Tab Appearance will be used to show the breadcrumbs (drop downs) also.</p> <p>Note: This problem has been corrected in 800xA Base 5.1 FP4 RevD RU2.</p>