

C:\ABB Industrial IT Data\Integrate IT Data\ITS LinkTool 5.1\ApplyReports\ [redacted] 2017-11-16-1 - Internet Explorer

C:\ABB Industrial IT Data [redacted] C:\ABB Industrial IT Data\Int... x

Apply report : [redacted]-2017-11-16-10-2-42.html

1) General

- At least some apply actions failed
- The configuration has been updated. Before using the system, please inspect the configuration carefully

2) Failed actions

- Update controller settings
 - Settings for controller [redacted] could not be implemented
 - Settings for controller [redacted] could not be implemented
 - Settings for controller [redacted] could not be implemented
 - Settings for controller [redacted] could not be implemented

3) Successfully completed actions

- Update MMS cross references
 - Update not necessary.
- Create OPC AutoLoad files
 - OPC AutoLoad files successfully created and distributed
- Update Log Configurations
 - Successfully updated history log configurations
 - Successfully updated event log configurations
 - Restart of history services not required

```
ITSLinkTool - Notepad
File Edit Format View Help
LOG 3, 2017-11-15 14:32:13:046
Configuration saved successfully
LOG 3, 2017-11-15 14:32:33:758
Adjusting soft controller configuration on SCM with configuration [redacted] at 172.16.[redacted]
LOG 3, 2017-11-15 14:32:33:775
Controller 2 defined
LOG 3, 2017-11-15 14:32:33:788
Controller 3 defined
LOG 3, 2017-11-15 14:32:33:801
Controller 4 defined
LOG 3, 2017-11-15 14:32:33:814
Controller 5 defined
LOG 1, 2017-11-15 14:32:33:825
An exception occurred when applying controller settings: The server threw an exception. (Exception from HRESULT: 0x80010105 (RPC_E_SERVERFAULT))
LOG 1, 2017-11-15 14:32:33:829
An exception occurred when applying controller settings: The server threw an exception. (Exception from HRESULT: 0x80010105 (RPC_E_SERVERFAULT))
LOG 1, 2017-11-15 14:32:33:833
An exception occurred when applying controller settings: The server threw an exception. (Exception from HRESULT: 0x80010105 (RPC_E_SERVERFAULT))
LOG 1, 2017-11-15 14:32:33:838
An exception occurred when applying controller settings: The server threw an exception. (Exception from HRESULT: 0x80010105 (RPC_E_SERVERFAULT))
LOG 3, 2017-11-15 14:33:15:499
winservice object terminated
LOG 3, 2017-11-15 14:33:15:500
Service supervision background thread has terminated
LOG 2, 2017-11-15 14:33:15:511
Supervision has been restarted
LOG 3, 2017-11-15 14:33:15:512
Service supervision background thread has started
```

Link Tool

File View Tools Help

Controller: Stop Start Cold Start System variables Log

Configuration Supervision Log

Item	Status	Description
Core Functionalities		
Simulator Link Server_Basic_AS [redacted]	Running	
Simulator Record Replay_Basic_AS [redacted]	Running	
Event Storage_AS [redacted]	Running	
Alarm Manager_AS [redacted]	Running	
Basic History_CS [redacted]	Running	
Lock Server_AS [redacted]	Running	
Event Collector_ABB 800xA Soft Alarms OPC Server_AS [redacted]	Running	
Soft Alarms_AS [redacted]	Running	
AC 800M Connectivity		
OPCDA_Provider_CS [redacted]	Running	
[redacted] OPC DA server	Running	
SP_Event Collector_CS [redacted]	Running	
[redacted] OPC AE server	Running	
[redacted]	AutoLoad	
[redacted]	AutoLoad	
[redacted]	AutoLoad	

Failed to execute command