

ABB LPLS Support Request SR-05573 rev -: PropertiesBaan, Arie
19-feb-2018

Name	SR-05573
State	Complete
Creator	NLArie
Assigned Supporter	ABBMichael
High Impact	No
Support Request Product	MNS iS
Aspect	Design Electrical
Component	MLink
Reason	Request for help / explanation
Part Number	
Title	Profibus Queries between Honeywell and ABB
Problem Description	Enclosed you find a document from Honeywell regarding redundand MLink MLink image = 1TGE131015R0002 MLink application = 1TGE131135R0001 MControl base version 7.40 OS version = 1.7 Factory FW ID = 2
Segment	Oil/Gas/Petrochemical
Project	Engie D15
Customer	NONE
Version	7.4
Resolution Action	Answer Request
Resolution Recommendation	19-Feb-2018 Hi Arie, sorry I can not support in this case, because we have no experience with RLM module. I have attached the manual I have downloaded from Intranet. The questions should be send to the ABB Automationteam. I was looking for contact, but this is the only link I found. http://www402.abbext.com/800xa-c432.aspx?_ga=2.160627320.413387884.1519027492-1486484432.1518447991
Reason For Rejection	
Timeline	0
Visibility	Public
Draft Rejection Comment	
Last Modified On	2/19/2018 10:59:10 AM