



Running Plausibility check



After right, clicking load "changed object" on PCS (AC800FR)



On "Commissioning Mode"

